

Xline Selection Bits - Pins				Sensor Number
S3	S2	S1	S0	
0	0	0	0	0 (Top Left)
0	0	0	1	1
0	0	1	0	2
0	0	1	1	3
0	1	0	0	4
0	1	0	1	5
0	1	1	0	6
0	1	1	1	7 (Top Center)
1	0	0	0	8
1	0	0	1	9
1	0	1	0	10
1	0	1	1	11
1	1	0	0	12
1	1	0	1	13
1	1	1	0	14 (Top Right)
1	1	1	1	15 (Bottom Center)